

| Site Name | Feature Location | 6 D's | Reasons | Existing species | Planting notes | Replant species |
|-------------|---------------------------|----------|--|----------------------|--|--------------------------------|
| STRUAN ROAD | Side of 62 Archer Lane | Damaging | Rooting above tarmac along kerbstones, cannot work round | Acer pseudoplatanus | Plant in new 800mm pit 10m toward Archer lane, (away from lamp and phone mast, chk map if req'd) | Acer rubrum 'Octobe Glory' |
| STRUAN ROAD | O/S 29-31 | Damaging | Kerbs displaced, f/w uplifted, potential 3rd party wall damage | Acer pseudoplatanus | Plant in new 800 pit o/s 29-31 (same as felled tree) | Acer rubrum 'October Glory' |
| STRUAN ROAD | O/S 17 | Damaging | Kerbs absent, completely unable to repair without unacceptable root damage | Platanus x hispanica | Plant in new 800 pit o/s 17-19 (same as felled tree) | Acer rubrum 'Octobel Glory' |